























NO.	Designation	Pieces	NO.	Designation	Pieces
1		X1	8		X2
2		X2	9		X2
3		X13	10	 ST4X12	X4
4	  ST4X10	X13	11		X1
5	  ST4X30	X7	12		X2 X2 X1 X1
6	 $\phi 6$	X7			X1 X1
7		X2			X1 X4 X2 X2 X1 X1
					X2 X2 X1 X4 X2 X1
				E	No handle
				 $\phi 6$ $\phi 3.2$	







1.







2.














7.



8.



9.



10.

i

24h 

